



Service Bulletin 011-7241

Telemetry Board Missing from Some Orion 7P Spares Kits 008-0143

Compliance:
Recommended*

ISSUE DATE:

March 31, 2009

AFFECTED PRODUCT(S)

Orion 7P Manipulator Systems

AFFECTED COMPONENT

Standard Orion 7P Spares Kits 008-0143

SERVICE ISSUE

Spares kits 008-0143 shipped between January 25, 2008 through February 26, 2009 are missing Telemetry Board 005-4645 (a component of the Orion 7P manipulator system Master Controller 101-5781-1).

FIELD ACTION

No field action is required. Sales orders for Spares Kits 008-0143 with the missing telemetry board have been identified. Telemetry Board 005-4645 will be supplied for each of these kits and shipped to the location where the original spares kit was sent. Each shipment will be identified with references to this bulletin and the original sales order.

If you have any questions or concerns, please contact our Customer Service Department at: customerservicebulletins@schilling.com

*BULLETIN STATUS LEVELS	
MANDATORY	Field action is MANDATORY to ensure personnel safety, equipment functionality, and/or continuation of warranty coverage.
RECOMMENDED	Field action is not required but is highly RECOMMENDED and will result in significantly increased levels of personnel safety and/or equipment functionality.
OPTIONAL	Field action may be useful under certain circumstances. Compliance is OPTIONAL and left to the discretion of the owner/operator.
ADVISORY	Bulletin contains advisory information to assist the owner/operator in more effective operation or service of the product. Compliance is not rated.

If you have any questions about this service bulletin, contact the Schilling Customer Service Department at:
Tel: +1 530 753 6718 (USA) or +44 (0) 1224 560 900 (UK)
Fax: +1 530-753-1534 (USA) or +44 (0) 1224 560 901 (UK)
e-mail: service.email@schilling.com • For bulletins & manuals online, go to: <http://www.schilling.com>

- Service Bulletin 011 – 7241

This page not used.